

CLASSIFIED MESSAGE

DATE 2235Z 23 NOV 64

SECRET

25X1A

TO : [REDACTED]
FROM : [REDACTED]
ACTION:
INFO :

TOR 2340Z 23 NOV 64

ROUTINE	
1	MD
2	11
3	260
4	26A
5	AC
6	EV
7	EV
8	EV

ROUTINE

IN 59088

25X1A

25X1A

25X1A

INFO

CITE

IDEALIST LOGS

25X1A

REF: [REDACTED]

1. PROBLEMS ENCOUNTERED WITH "UP DATED" SEXTANTS ARE:
 - A. EXCESSIVE TENSION ON ELEVATION WORM GEAR.
 - B. EXCESSIVE BACK LASH BETWEEN RELATIVE BEARING FACE GEAR AND IDLER SPUR GEAR CAUSING ERROR IN HEADING.
 - C. UNABLE TO KEEP BUBBLE SIZE CONSTANT BY ADJUSTING THERMOSTAT.
2. WE HAVE FIVE "UP DATED" SEXTANTS, S/N 504, 505, 515, 517 AND 518 AND ALL REQUIRED MAINTENANCE ON BUBBLE ASSEMBLY EXCEPT S/N 518. ALL PROBLEMS TO DATE HAVE BEEN SOLVED EXCEPT BUBBLE MALFUNCTION WHICH [REDACTED] HAS ASSURED A SOLUTION ASAP.

25X1A
END OF MESSAGE

SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNgrading
AND DECLASSIFICATION